# Oil Field Environmental Incident Summary

**Responsible Party:** STATOIL OIL & GAS LP **Well Operator:** STATOIL OIL & GAS LP

Well Name: LIFFRIG 29-20 #4H

Field Name: ALGER Well File #: 22461

Date Incident:2/16/2015Time Incident:21:30Facility ID Number:County:MOUNTRAILTwp:156Rng:93Sec:29Qtr:

Location Description: N/A

Submitted By: Derrick McBride Received By:

Contact Person: Derrick McBride

6300 BRIDGE POINT PKY, BLDG 2

SUITE 500

AUSTIN, TX 78730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 1600 Feet **Distance Nearest Water Well:** 1600 Feet

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 3 Barrels 3 Barrels

Other

**Description of Other Released Contaminant:** 

N/A

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

N/A

Areal Extent:

N/A

# Potential Environmental Impacts:

N/A

# Action Taken or Planned:

Recovered all fluids and contaminated soil. Retrained crew to ensure all valves are closed and lines are capped before proceeding to the next step in their job task.

Wastes Disposal Location: Prairie Disposal

Agencies Involved:

# **Updates**

Date: 2/17/2015 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

# Notes:

Release, due to an on-location valve/piping leak, remained on location according to the report. NDIC retains oversight.